









①




②



③




④




2 pcs

⑤



⑥



⑦



4 pcs

A M6x42



x12

B Ø15x12



x12

C 4x16



x24

D Ø6x40








x12

E M5x40




x6

1 PCS

M6X42mm



1




2

C 4x16




x24





3



A M6x42



x4

B $\phi 15 \times 12$




x4

D $\phi 6 \times 40$



x4

4



A M6x42



x2

B $\phi 15 \times 12$



x2


D $\phi 6 \times 40$



x2



5




E M5x40



x6

6



A M6x42



x2

B Ø15x12



x2


D Ø6x40



x2



7



A M6x42



x4

B Ø15x12



x4

D Ø6x40



x4

8

