



Assembly Instructions



Hardware List

A



82 PCS

B



82 PCS

C Ø6x30mm



22 PCS

D



8 PCS


E M6x22mm



4 PCS

F

M4



1 PC

G

M3



1 PC

H



4 PCS

I



4 PCS

J




2 PC

K




4 PCS

L




4 PCS













M





8 PCS






Parts List

 <p>1 PC</p>	 <p>1 PC</p>	 <p>1 PC</p>	 <p>2 PCS</p>
 <p>2 PCS</p>	 <p>2 PCS</p>	 <p>2 PCS</p>	 <p>2 PCS</p>
 <p>2 PCS</p>	 <p>2 PCS</p>	 <p>4 PCS</p>	 <p>2 PCS</p>





Step 1







Step 2




Step 3






Step 4




Step 5





X2




Step 6





X2




Step 7





X2




Step 8






X2




Step 9





X2






Step 10




X2





Step 11






Step 12






X2




Step 13




Step 14






Step 15



Step 16



Step 17



Step 18

