


Assembly Instructions



Computer PC Table


Special Warnings

- Keep your furniture out of direct sunlight. Please use desk pads and coasters to protect the surface from dents, scratches, and moisture from hot or cold liquids.
- For cleaning, wipe the surface with a damp (not wet) cloth or wipe dry with a clean lint free cotton cloth. Window cleaning liquid or a similar cleaning liquid can be used to clean glass surface.


Operation Instructions

- Please check that all parts are present before you start the assembly of your furniture. For the protection of your furniture, place all parts on a clean and smooth surface to prevent any damage.
- Please periodically check all fitting and re-tighten as necessary.
- Please assemble the table by 2 persons or more.
- Do NOT over tighten hardware.


①




②




③




④




⑤




⑥




⑦




⑧




9




10




11




12




13




14




15




16




17




18




19




20




21







22




23








16'

2 Sets




PART	ITEM	QTY.		PART	ITEM	QTY.	
A	M6X50	10		I		24	
B	M6X35	12		J		36	
C	M6X30	22		K	6X40	8	
D		4		L	M6	4	
E	M5X40	18		M		2	
F	M4X20	4		N		12	
G	M3.5X14	16		O		10	
H	M3X24	4		P			


6X45mm bolt installation as below



1




.SCREWS	
I	
8 PCS	
J	
8 PCS	



x 2 Drawers

2


.SCREWS	
E	
M5X40	
8 PCS	



x 2 Drawers

3


.SCREWS	
G	
M3.5X14	
8 PCS	



x 2 Drawers

4

.SCREWS	
F	
M4X20	
4 PCS	
M	
2 PCS	




x 2 Drawers

5

. SCREWS


B M6X35
8PCS

L 4PCS



6

. SCREWS

G M3.5X14
8PCS



7

. SCREWS

I 4PCS


J 4PCS

K 4PCS




8



. SCREWS

E M5X40
4PCS

9




. SCREWS	
I	4 PCS
J	4 PCS
K	4 PCS




10

. SCREWS	
C	M6X30
	4 PCS



11


. SCREWS	
C	M6X30
	2 PCS



12

. SCREWS


H	M3X24	
	4 PCS	
D		
	4 PCS	



13

. SCREWS


N		
	4 PCS	
J		
	4 PCS	



14

. SCREWS


I		
	4 PCS	
A	M6X50	
	2 PCS	
J		
	4 PCS	
O		
	2 Stck	




15

. SCREWS

C	M6X30	
	4 PCS	
E	M5X40	
	4 PCS	




16




. SCREWS	
A	M6X50 8 PCS
B	M6X35 4 PCS
O	8 Stck

17




. SCREWS	
J	2PCS
C	M6X30 8PCS
N	2PCS

18




. SCREWS	
J	2PCS
N	2PCS


19



20



21



22

