




QUESTIONS OR CONCERNS?

IMPORTANT! Please read all instructions before use and keep this manual for future reference. Your satisfaction is very important to us. If you have any issues, **PLEASE CONTACT US** at **care@oakhamdesign.com** before initiating a **RETURN**.

ATTENTION



Attention Customers living in the United States and Canada

If you are missing parts, hardware, or if your product has been damaged during shipping



DO NOT RETURN YOUR PRODUCT

The store does not stock parts and may not be able to help you. Please contact us directly and **we will ship you the parts** you need to your shipping address **at no cost to you**. For the quickest and most efficient service, please reach out to us at **care@oakhamdesign.com**. We're here to help!

※ **Stay Scratch-Free: Safeguard Your Furniture by Assembling on Carpet.**



※ **Stuck in Assembly Limbo? Check out our website or contact our support team for quick solutions!**




WARNING : ASSEMBLY NOTICE

Attention

Important Instructions for Assembling Your Furniture To ensure the longevity and integrity of your MDF furniture, please adhere to the following guidelines:

DO NOT USE AN ELECTRIC DRILL



Using an electric drill can cause irreversible **damage to the MDF boards**, leading to compromised structural integrity and potential voiding of your warranty.


IF AN ELECTRIC DRILL MUST BE USED

- **Set to Lowest Torque Setting :**

Ensure your drill is set to the lowest possible torque setting to avoid over-tightening and damaging the material.

- **Proceed with Caution :**



Carefully monitor the drilling process to prevent excessive force and damage.










For best results and to avoid any damage, we highly recommend using the provided manual tools or a handheld screwdriver.









Thank you for your attention and understanding.

PARTS LIST













PARTS LIST

Item:	Reference Image	Qty
1		x1
2		x1
3		x1
4		x1
5		x1
6		x1
7		x5


Item:	Reference Image	Qty
8		x5
9		x5
10		x5
11		x5
12		x5
13		x1
14		x1
15		x2

HARDWARE
LIST

A  x49	B  x49	C  ø8*30MM x8	D  M4*35 x25
E  M3*12 x70	F  x5	G  x12	H  x2
I  M3*16 x12	J  x49	DL 	CL 
CR 	DR 		


1

1




x1

14




x1

A




x6




2

2



x1

A




x9

E





x15

CL




x5




3

3



x1

A




x9

E





x15

CR



x5



4

4

14

B



C

x1

x1


x2

x2




5

2




x1

5




x1

6




x1

13



x1

B





x9

C




x1




6

15




x1




7

③



x1

B






x9

C




x1




8

15




x1




9

①



x1

B







x4

C



x4






11

⑦


A

B


E




x5



x25



x25




x40


F

DL


DR





x5




x5




x5



x 5






x 5




x 5

12




13

G



x12

H




x2


I





x12




H




14



15^H



1:



2:

