


Assembly Instruction




NO.	QTY.	LINEDRAWING
(A)	34	
(B)	34	
(C)	32	 8x40
(D)	24	 3.5x30
(E)	16	 25x6
(F)	16	 3.5x15
(G)	8	
(H)	12	
(I)	8	





Hammer and Screwdriver
are not included !!





Assembly Instruction





1





2




3





4







7





X2




5




8



6




9



I		F	
8x		16x	

10



G	
8x	

