



DJYC2520


ASSEMBLY INTRODUCTION



Exploded View



Fitting




A x104
M6 x 35 mm



B x104
φ15 x 9.5 mm



C x22
φ6 x 30 mm




D x64
φ4 x 35 mm



E x144
φ3 x 12mm



F x12
φ6 x 50 mm



G x2




H x4
φ4 x 12 mm




I x2
φ6 x 30 mm



J x2
φ4 x 40 mm




K x16



CL x12
330 mm



CR x12
330 mm








DL x12
330 mm





DR x12
330 mm

Step 1




x2


Step 2




x2




Step 3









Step 4




Step 5




Step 6




Step 7




Step 8




Step 9







Step 10




Step 11





Step 12







Step 13




Step 14




Step 15




Step 16



x12




Step 17



x12




Step 18



x12


Step 19




x4




Step 20



Step 21



Step 22



Step 23

