























mm
inch
x1






A 	B 	C 	D 
E 	F 	G 	H 
I 	J 	K 	Lx4 
Mx2 	Nx4  M4x $\frac{5}{0.2}$	Ox2 	Px2 
Qx4 	Rx23  M5x $\frac{12}{0.5}$	Sx2 	Ux4 
		Tx2 	Vx4 



1




x4




2




3




4





5





6





7



8




9




Rx4 M5x $\frac{12}{0.5}$


10




11




12




13




14



15



16



17

