










STEP 1






A	×8
	
ø6*35mm	

STEP 2




A	×2	E	*8	M	×2	N	×2
							
ø6*35mm		3. 5*12mm		L350mm		L350mm	


STEP 3






E	*4	R	×2
			
3.5*12mm		L350mm	

STEP 4




A	×2	E	*4	Q	×2
					
ø6*35mm		3.5*12mm		L350mm	

STEP 5




H	*1	I	*4	J	*4	K	*2
							
M4X55		M6*15mm		M6*20mm		M6*35mm	

STEP 6






B	*4	C	*4
			
φ 15X12		φ 7 8X30	

STEP 7




STEP 8




C	*4	G	X4
			
Φ 7. 8X30		Φ 7X47	

STEP 9





B	*4	C	*4
			
φ 15X12		φ 7.8X30	

STEP 10




STEP 11





C	*4	G	X4
			
Φ 7. 8X30		Φ 7X47	

STEP 12




B	*4	C	*2
			
Φ 15X12		Φ 7. 8X30	

STEP 13




I	*8
M6*15mm	


STEP 14




K	*4
M6*35mm	


STEP 15




A	X8	D	X8
			
Φ 6X35		Φ 15X10	

STEP 16




E	*4	F	*8	L	× 2
					
3. 5*12mm		4*35mm		150*30*20mm	


STEP: 17





E	*8	O	×2	P	×2
					
3.5*12mm		L350mm		L350mm	

STEP: 18



A	×4	D	×4	F	×4
					
φ6*35mm		φ15*10mm		φ4*25mm	

STEP 19



E	×2	L	×1	S	×2
					
ø 3.5*12mm		150*30*20mm		L336mm	

STEP 20

