



INSTALLATION INSTRUCTIONS

ASSEMBLY DIAGRAM



PARTS LIST


No.	Description	QTY	No.	Description	QTY	No.	Description	QTY
1		1	8		5	Α	+1(spare)	12
						В	+1(spare)	34
2		1	9		6	С	+1(spare)	34
						D	3x12mm +1(spare)	48
3		1	10		6	Е	4x30mm +1(spare)	30
						F	\bigcirc	6
4		1	11		6	G	(4x16mm	6
						Η	@mmanagement	5
5		1	12	0	6	I	(2000) 4x12mm	2
						J		2
6		1	13		6	K		2
						L	@ June 1 4x35mm	2
7	5	2	14		2	М	+1(spare)	10
						Ζ	3x16mm +1(spare)	10
			15		2	CL		6
						CR		6
						DL		6
						DR	8:	6





YOU MAY NEED (NOT SUPPLIED)




INSTALLATIONS












5PCS


Н %










STEP 8










STEP 10





STEP 13 X6






STEP 14


x6






WARNING: Anti-tipping hardware is only a deterrent. It is not a substitute for proper adult supervision.

Young children may be injured by tipping furniture and the use of a tipping restraint is highly recommended. This hardware, when properly installed, could provide protection against the unexpected tipping of furniture due to




STEP 15 X6





STEP 16 X6

















Thank you very much for purchasing from us.

We have always been trying to provide the best service and reliable products for every customer.

However, accident may happen sometimes, please contact us to resolve any issue before leaving a negative feedback.

Many thanks and welcome to our shop again!