



Assembly Instruction





x2



















Components - Fittings

Please check you have all the panels listed below


Note: The quantities below are the correct amount to complete the assembly. In some cases, more fittings may be supplied than required.

 A:50pcs	 B:50pcs	 Ø5x40mm C: 32pcs	 Ø3x12mm D:16pcs	 E: 4pcs	 Ø4x10mm F: 4pcs
 G:2pcs	 Ø4x25mm H:4pcs	 I: 8pcs	 Ø3x16mm J:8pcs	 Ø6x30mm K: 49pcs	 Ø4x30mm L:12pcs
 M:4pcs	 Ø4x15mm N:24pcs	 O:8pcs	 P:4pcs	 Q:1pc	 Ø4x25mm R:2pcs


Assembly Instruction

					
1: 1pc	2: 1pc	3: 1pc	4: 1pc	5: 1pc	6: 1pc
					
7: 1pc	8: 4pcs	9: 1pc	10: 1pc	11: 1pc	12: 1pc
					
13: 2pcs	14: 2pcs	15: 1pc	16: 4pcs	17: 1pc	18: 1pc
					
19: 1pc	20: 1pc	21: 1pc	22: 1pc	23: 1pc	24: 2pcs
					
25: 3pcs	26: 1pc	27: 1pc	28: 2pcs	29: 2pcs	30: 2pcs
					
31: 2pcs	32: 2pcs	33: 2pcs			

Step 1




(A)



x12

Step 2



(B)




x8

(K)



x3


Step 3




(C)  **x8**
 $\varnothing 5 \times 40 \text{ mm}$



(K)  **x8**

Step 4





(D)  **x8**
 $\varnothing 3 \times 12 \text{ mm}$

(P)  **x4**



Step 5






(A)  x10

(E)  x4


(F)  $\varnothing 4 \times 10 \text{ mm}$ x4

Step 6

P₂







(D)  x8
 $\varnothing 3 \times 12 \text{ mm}$

(P)  x4

x2


Step 7



x2

(B)		x10
(K)		x2
(L)	 Ø4x30mm	x12


Step 8




(B)  x4


(K)  x6

Step 9



Step 10





(A)  x14


(B)  x6

(K)  x4

Step 11









(A)  x10

(C)  x16
Ø5x40mm


(K)  x8

Step 12




(A)		x4
(C)	 Ø5x40mm	x4
(B)		x6
(K)		x6

Step 13




(R)  $\varnothing 4 \times 25 \text{mm}$ x2

Step 14



(B)  x8


Step 15




(C)  x4
Ø5x40mm

(K)  x4

Step 16




Step 17





(B)		x4
(K)		x4

Step 18



B		x4
K		x4








Step 19



(M)  x4

(N)  x8
Ø4x15mm

Step 20





(G)  x2

(H)  x4
Ø4x25mm


(M)  x4

(N)  x16
Ø4x15mm

Step 21



Step 22



I  x8

J  $\varnothing 3 \times 16 \text{ mm}$ x8

Step 23

