




# ASSEMBLY INSTRUCTION












Minimum no. 2 of people  
recommended to assemble  
this product: Approx.  
assembly time: 60 mins














# PART LIST MF314054




<p>1</p>  <p>4PCS</p>	<p>2</p>  <p>2PCS</p>	<p>3</p>  <p>2PCS</p>
<p>4</p>  <p>2PCS</p>	<p>5</p>  <p>26PCS</p>	<p>6</p>  <p>8PCS</p>
<p>7</p>  <p>1PC</p>	<p>8</p>  <p>1PC</p>	<p>9</p>  <p>2PCS</p>



# HARDWARE LIST MF314054

<p>A</p>  <p>16PCS M<math>\frac{1}{4}</math>"X50</p>	<p>B</p>  <p>4 PCS M<math>\frac{1}{4}</math>"X40</p>	<p>C</p>  <p>8 PCS M<math>\frac{1}{4}</math>"X35</p>	<p>D</p>  <p>16PCS M<math>\frac{1}{4}</math>"X15</p>
<p>E</p>  <p>4PCS Ø32x20</p>	<p>F</p>  <p>1PC M4X23X57</p>	<p>G</p>  <p>M<math>\frac{5}{16}</math>"xØ50x70H 2 PCS</p>	<p>H</p>  <p>M<math>\frac{5}{16}</math>"xØ50x70H 2 PCS</p>
<p>i</p>  <p>1PC 13mm</p>			


STEP 1



2 SET

A	B	E
		
M $\frac{1}{4}$ x50	M $\frac{1}{4}$ x40	Ø32x20
8 PCS	4 PCS	4 PCS






STEP 2

D

M $\frac{1}{4}$ x15
12 PCS







# STEP 3

A
 M $\frac{1}{4}$ "x50
8 PCS







STEP 4

G	H
 M <sup>5</sup> / <sub>16</sub> "xØ50x70H	 M <sup>5</sup> / <sub>16</sub> "xØ50x70H
2 PCS	2 PCS



STEP 5

C	D
 M <sup>1</sup> / <sub>4</sub> "x35	 M <sup>1</sup> / <sub>4</sub> "x15
8 PCS	4 PCS



# STEP 6

