




ASSEMBLY INSTRUCTION

MF314860 / MF314861














Minimum no. 2 of people
recommended to assemble
this product: Approx.
assembly time: 60 mins

















PART LIST MF314860

5	 1PC	9	 1PC	10	 1PC
11	 1PC	12	 1PC	13	 4PCS
14	 1PC	15	 1PC	16	 1PC
17	 1PC	18	 1PC	19	 1PC
20	 1PC	22	 1PC	23	 1PC
24	 1PC	29	 2PCS		

HARDWARE LIST MF314860



A	 12PCS M $\frac{1}{4}$ "X55	B	 2PCS M $\frac{1}{4}$ "X50	C	 37PCS M $\frac{1}{4}$ "X40	D	 18PCS M $\frac{1}{4}$ "X25
E	 22PCS M $\frac{1}{4}$ "X15	F	 4PCS $\frac{1}{4}$ "x7	G	 58PCS M4x15	H	 14PCS M4x20
i	 2PCS #40x40x13	J	 1PC M4X23X57	K	 8 PCS 15x20x40H	L	 16 PCS M4x15
M	 3x50x50 3 PCS						

PART LIST MF314861

1	 1PC	2	 1PC	3	 1PC
4	 1PC	6	 2PCS	7	 2 PCS
8	 2 PCS	21	 1PC	25	 6PCS
26	 12PCS	27	 1PC	28	 1PC
30	 2PCS	31	 2PCS	32	 2PCS
33	 2PCS				



STEP 1

E	M
 M $\frac{1}{4}$ "x15	 3x50x50
6 PCS	3 PCS





STEP 2

E
 M $\frac{1}{4}$ "x15
12 PCS





STEP 3

A	i
 M $\frac{1}{4}$ "x55	 #40x40x13
2 PCS	1 PC





STEP 4

A	i
 M $\frac{1}{4}$ "x55	 #40x40x13
2 PCS	1 PC





STEP 5

A	B
	
M ₄ ¹ x 55	M ₄ ¹ x 50
8 PCS	2 PCS



STEP 6

C	F
 M $\frac{1}{4}$ "x40	 $\frac{1}{4}$ "x7
8 PCS	4PCS




STEP 7

G

M4x15

12 PCS





STEP 8

C

M $\frac{1}{4}$ "x40

4 PCS





STEP 9

C

M $\frac{1}{4}$ "x40

4 PCS




STEP 10

G



M4x15

12 PCS





STEP 11

C	E
 M $\frac{1}{4}$ "x40	 M $\frac{1}{4}$ "x15
4 PCS	4 PCS



STEP 12



G
 M4x15
8 PCS



STEP 13

C


M $\frac{1}{4}$ "x40
8 PCS



STEP 14

G



M4x15
12 PCS



STEP 15

H



M4x20
14PCS



STEP 16

C



M $\frac{1}{4}$ "x40
3 PCS



STEP 17

C


M $\frac{1}{4}$ "x40
6 PCS




STEP 18

2 SET

K	L
	
15x20x40H	M4x15
8 PCS	16 PCS



360°




STEP 19

2 SET

D

M4x25
18 PCS



60%




STEP 20

2 SET

G

M4x15
14 PCS



360°



STEP 21

