


ASSEMBLY INSTRUCTIONS


TWIN LOFT BED





Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Separate, identify and count all parts and hardware.

Compare with the parts list to be sure all parts are present.


"DO NOT TIGHTEN SCREWS UNTIL COMPLETELY ASSEMBLED"




* Use of power tool to assemble this product will invalidate any claim and damage this product making unsafe !!!
* Please assemble on a clean soft surface to avoid damage.



Tools Required



(Not included)




(Not included)

IMPORTANT:


PLEASE READ INSTRUCTION BEFORE STARTING THE ASSEMBLY


Part List - TWIN LOFT BED



Identifying the Hardware—Identify the hardware using the illustrations below.


A  Qty **08**
10 x 40 Wood Dowel


B  Qty **08**
3,5 x 16 Screw


C  Qty **50**
4,0 x 35 Screw


D  Qty **02**
Spacer

E  Qty **02**
Hex Screwdriver

F  Qty **36**
4,0 x 40 Screw


G  Qty **08**
1/4 x 100 Screw

H  Qty **03**
Screw union


I  Qty **08**
7,0 x 50 Screw


J  Qty **08**
1/4\"

01




E  Qty **01**
Hex Screwdriver


I  Qty **02**
7,0 x 50 Screw


L  Qty **02**
7,0 x 80 Screw

02






E  Qty **01**
Hex Screwdriver

I  Qty **02**
7,0 x 50 Screw





L  Qty **02**
7,0 x 80 Screw

03



A  10 x 40 Wood Dowel Qty **08**

04



E



Qty
01

G



1/4 x 100 Screw

Qty
04





J



1/4" Half Moon

Qty
04

05



E



Qty
01

G



1/4 x 100 Screw

Qty
04

J



1/4" Half Moon

Qty
04





L




7.0 x 80 Screw

Qty
06



06





F  **4,0 x 40 Screw** **Qty 11**

M  **4,0 x 25 Screw** **Qty 03**




07




F  **4,0 x 40 Screw** **Qty 09**



M  **4,0 x 25 Screw** **Qty 03**

08



C  **4,0 x 35 Screw** Qty **02**



09




E  **Qty 02**
Hex Screwdriver




H  **Qty 03**
Screw union


10




C  **4,0 x 35 Screw** Qty **12**




11




B  **3,5 x 16 Screw** Qty **08**


K  **Plates** Qty **04**




12






C  4,0 x 35 Screw Qty 12


E  Hex Screwdriver Qty 01


I  7,0 x 50 Screw Qty 04




13





D  Spacer Qty 02



C  4,0 x 35 Screw Qty 24



14



Alignment



F



4,0 x 40 Screw

Qty

16