




INSTRUCTIONMANUAL




■ Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.



■ If you have any question, please feel free to contact us. Mail us support@ironck.com

MADE IN CHINA


HARDWARELIST




① x1PCS




② x1PCS




③ x1PCS




④ x4PCS




⑤ x4PCS




⑥ x2PCS




⑦ x6PCS



⑧ x2PCS



⑨ x2PCS




⑩ x2PCS


LISTPARTA




M6*10mm
A x 2PCS




M6*20mm
B x 4PCS




M6*28mm
C x 28PCS




M8*30mm
D x 6PCS



M6*35mm
E x 8PCS





M6
F x 1PCS





M8
G x 1PCS

1





2





x 2

3




4



x 2


5



7		6PCS
10		2PCS
C		12PCS
E		8PCS

x 2



6



6		2PCS
C		8PCS

x 2

7



x 2