









Ax1 	Bx1 	Cx1 	Dx1 
Ex1 	Fx1 	Gx1 	Hx2 
Ix1 	Jx1 	Kx1 	Lx1 
Mx1 	Nx2 	Ox4  M3x $\frac{25}{1.0}$	Px11  M3x $\frac{20}{0.8}$
Qx11  M2.5x $\frac{18}{0.7}$	Rx4  M2x $\frac{10}{0.4}$	Sx4  M2x $\frac{12}{0.5}$	 mm inch x1






6




Qx11

7



8



9

