


Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A triangle with an exclamation mark points to a box containing:
 - An icon of an L-shaped metal bracket.
 - An icon of a power drill with a slash through it, indicating that a power drill should not be used.
- Warning 2:** A triangle with an exclamation mark points to a box containing:
 - An icon of a rectangular block being placed on a textured surface.
 - An icon of a rectangular block with a slash through it, indicating that the block should not be placed on a soft or uneven surface.
- Time:** A clock icon is shown next to the text "20'", indicating an estimated assembly time of 20 minutes.
- Person:** An icon of a person is shown next to the number "1", indicating that one person is required for assembly.

A




x 1

B




x 4


A



B x 4




C



**M6
x
20**

x 12

D



x 1

1

