



USER'S MANUAL




PARTS LIST


A x 4




B x 4




C x 2




D x 2




E x 2




F x 2




G x 2



H x 1




I x 1




PARTS LIST



J x 2



K x 1



TOOLS




Hardware

① x 8



(M4 x 12)

② x 24




(M6 x 12)

③ x 12




(White) (M6 x 40)

④ x 12



(M6 x 45)




⑤ x 8



(M6 x 60)



Step 1

x2




Step 2

x2



Step 3


x2



4 x 4


Step 4

x2






3 x 12
(White)


Step 5



Step 6




Step 7




② x 4

Step 8




① x 8

Step 9




Step 10




② x 8

Step 11




2 x 4


Step 12




Step 13




Step 14




Step 15



Step 16



Step 17



ACCOMPLISHED

