
















 A(X2)		 D(X1)	
 B(X2)		 J(X1)	
 G(X4)	 F(X4)	 (X1)1286X15X30	
 T(X9)	 E(X1)	 (X2)1200X15X30	
 H(X2)	 G(X1)	 I(X1)	
	 M4x13mm (X35)		


1




A(X1)




(X1)1200X15X30




T(X2)




M4x13mm
(X4)




2




D(X1)



3




A(X1)




(X1)1200X15X30




T(X3)




M4x13mm
(X6)




4




5




B(X2)




G(X4)




6




7






8







F(X4)




9	 I(X1)	 M4x13mm (X1)
--------------	--	---




10	 J(X1)	 (X1)1286X15X30	 T(X4)	 M4x13mm (X8)
---------------	---	---	---	--




11




G(X1)




E(X1)




M4x13mm
(X2)




12




H(X2)



M4x13mm
(X4)





13



M4x13mm
(X10)

J

B



14

