











 <p>A line drawing of a power drill with a diagonal slash through it, indicating that power tools should not be used for assembly.</p>	 <p>A warning triangle containing an exclamation mark.</p>	 <p>A clock face showing approximately 1:50.</p>
  <p>Two icons: a rectangular block on a textured surface (representing glue) and a rectangular block with a staple being driven into it. Both are crossed out with a diagonal slash, indicating that glue and staples should not be used.</p>	 <p>A warning triangle containing an exclamation mark.</p>	 <p>A simple line drawing of a person.</p>





15'

1




A	B	C	D
			
x 1	x 1	x 1	x 1

1



2



!

