





Assembly Instructions



Desk


Warm Tips

- 1. Carefully read these instructions and keep them for future reference.**
2. Check the parts list and confirm everything's there before starting assembly.
3. When assembling, put all parts on a soft, smooth surface like a carpet to avoid scratches.
4. Don't fully tighten screws until all parts are confirmed in place to avoid misalignment.





We recommend using hand tools for assembly.


If an electric screwdriver is used, reduce power and torque to avoid damage to the product.



Install the Anti-Tip Straps

Using the anti-tip straps can reduce the risk of tipping over but can not eliminate it.



























⚠ Caution

Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for a free replacement if you encounter any damaged or missing parts.

Hardware List


 <p>1 1pc</p>	 <p>2 1pc</p>	 <p>3 1pc</p>
 <p>4 1pc</p>	 <p>5 1pc</p>	 <p>6 1pc</p>
 <p>7 1pc</p>	 <p>8 2pcs</p>	 <p>9 1pc</p>
 <p>10 2pcs</p>	 <p>11 2pcs</p>	

Hardware List


 A 2pcs	 B 10pcs	 C 2pcs
 D 24pcs	 H 2pcs	 I 2pcs
 L 4pcs	 V 4pcs	 Y 4pcs
		

Installation of Cams and Pins



Screw the pin into the hole. To set the cams correctly, ensure that the arrow on the cam is opening to the hole of the pin it is locking. Lock the cam by turning the cam head with a screwdriver until it is tightened. Please do not use an electric screwdriver to assemble the unit.




Read each step carefully before starting. It is very important that each step of instruction is performed in the correct order. If these steps are not followed in sequence, assembly difficulties will occur.



1





Ix2




Yx4

2





Dx12

3




Bx2


4




Ax2



Bx2





Cx2





Hx2

5




Dx12


6



Bx6



Lx4



Vx4

Thank you for your support!

