












Assembly Instruction




NO.	QTY.	LINEDRAWING
(A)	34	
(B)	34	
(C)	32	8x40 
(D)	24	3.5x30 
(E)	16	25x6 
(F)	16	3.5x15 
(G)	8	
(H)	12	
(I)	8	





Hammer and Screwdriver
are not included !!





Assembly Instruction




1





2




3



4




5



X2



A	B	C	H
6x	6x	4x	6x

6





C
8x

7





E
16x



8




D
16x


9



I		F	
	8x		16x

10



G	
	8x

