





CAUTION:When tightening the screws, tighten sequentially. Do not tighten any screws fully and then towards the next one.when every part is OK, then tighten all the screws.

NFN012
































×2




×2



①  1PC	②  1PC	③  1PC	④  1PC
⑤  1PC	⑥  1PC	⑦  1PC	⑧  1PC
⑨  2PCS	⑩  1PC	⑪  2PCS	⑫  2PCS
⑬  3PCS	⑭  2PCS	⑮  2PCS	⑯  2PCS
⑰  2PCS	⑱  2PCS	⑲  2PCS	⑳  2PCS

②1  2PCS	②2  2PCS	②3  2PCS	
---	---	--	--


A×47 +1	B×2	C×2	D×38 +1	E×35 +1
 φ6×35mm			 φ3×12mm	 φ4×30mm
F×34 +1	G×47 +1	H×2	I×8 +1	J×27 +1
 φ6×30mm	 φ15×10mm	 φ6×50mm	 φ8×30mm	 φ3×12mm
K×4	L×2	M×4 +1	N×2	O×8 +1
		 φ4×18mm		 φ4×12mm
P×2	Q×2	R×2	S×2	T×1
	 φ4×8mm			

1





A×4	B×1	C×1	D×4
			
Ø6×35mm			Ø3×12mm

2




Attention:


No. 3 is ONLY ONE, please install B/C track on the front and back side of No. 3 board respectively.

B×1	C×1	D×6
		
		Ø3×12mm


3

 $E \times 1$  $\phi 4 \times 30\text{mm}$

4

 $F \times 1$  $\phi 6 \times 30\text{mm}$ $G \times 1$  $\phi 15 \times 10\text{mm}$

5



F × 1



φ6 × 30mm

G × 1




φ15 × 10mm

H × 2



φ6 × 50mm

6



F × 2




φ6 × 30mm

G × 2



φ15 × 10mm


7



A×6




8



F×2




G×6





I×4







$E \times 6$	$F \times 2$	$I \times 4$
		
$\phi 4 \times 30\text{mm}$	$\phi 6 \times 30\text{mm}$	$\phi 8 \times 30\text{mm}$


10



11



12




F x 3

 $\phi 6 \times 30\text{mm}$

G x 3

 $\phi 15 \times 10\text{mm}$

13




F x 3

 $\phi 6 \times 30\text{mm}$

G x 3

 $\phi 15 \times 10\text{mm}$



F×4




ø6×30mm

G×11




ø15×10mm


15



16




17



J×27


 $\phi 3 \times 12\text{mm}$


18



E×8




 $\phi 4 \times 30\text{mm}$

19




E × 12	F × 12
	
φ4 × 30mm	φ6 × 30mm

20



A × 12	D × 8	K × 4
		
φ6 × 35mm	φ3 × 12mm	

21



×2

F×4

G×12




φ6×30mm



φ15×10mm

22



×2



L×2

M×4





φ4×18mm



23





24




25




26



27




×2




×2



E×8	P×2	Q×2
		
φ4×30mm		φ4×8mm

28



×2



D×12	R×2	S×2
		
φ3×12mm		

