


















mm
inch




x2

Ax1  $\frac{1100 \times 430}{43.3 \times 16.9}$	Bx1 	Cx1  $\frac{1050 \times 500}{41.3 \times 19.7}$	Dx1  $\frac{1050 \times 500}{41.3 \times 19.7}$
Ex1 $\frac{1100}{43.3}$  $\frac{1050}{41.3}$ $\frac{1100/1050 \times 500}{43.3/41.3 \times 19.7}$	Fx1 	Gx1  $\frac{1050 \times 200}{41.3 \times 7.9}$	Hx1 
Ix1 	Jx1 	Kx4 	Lx3 
Mx6 	Nx3 	Ox37  $M6 \times \frac{25}{1.0}$	Px5  $M6 \times \frac{45}{1.8}$
Qx24  $M6 \times \frac{15}{0.6}$	Rx71  M6	Sx5  M6	Tx1  M6
Ux1  M6	Vx2  $\frac{1050 \times 485}{41.3 \times 19.1}$	Wx5  $\frac{400 \times 400}{15.7 \times 15.7}$	Xx3  $\frac{350 \times 350}{13.8 \times 13.8}$





1




2







3




50%




4












50%













6



7



8



9

