








# 5 DRAWER DRESSER Assembly Instructions



Page 1 of 3

Made in Vietnam



## Components and Hardware List

Ø6x20 Bolt	Flat Washer	Spring Washer	Allen Key	Handle	Ø4x25 Bolt
					
<b>A</b> 16 PCS	<b>B</b> 16 PCS	<b>C</b> 16 PCS	<b>D</b> 01 PC	<b>E</b> 08 PCS	<b>F</b> 08 PCS






# 5 DRAWER DRESSER Assembly Instructions

Page 2 of 3

Made in Vietnam

## STEP 1

1



# 5 DRAWER DRESSER Assembly Instructions

Page 3 of 3

Made in Vietnam

## STEP 2

