




ASSEMBLY INSTRUCTIONS






1

×1




2

×1




3

×1




4

×2




5

×2




6

×2




7

×3




8

×2




9

x 4




10

x 4




11

x 2




Hardware List

A




8+1
1/4x50mm

B




20+2
1/4x40mm

C




22+2
1/4x18mm

D




36+2
M5x18mm

E




x1
M4


STEP 1




STEP 2



STEP 3




STEP 4




STEP 5

PATCH ALL THE SCREWS INTO POSITION THEN TIGHTEN THE SCREWS AGAIN



Tighten the locating screw first




D




× 24


STEP 6






STEP 7




STEP 9



STEP 10



STEP 11



x2

