








A



55PCS


B



55PCS

C

8*40



41PCS

D

3.5*14



32PCS

E



2PCS

F

6*25



8PCS

G

8*25



4PCS

H



8PCS


I

3*12



















8PCS


J



1PCS


1  900*300 1PS	2  900*209 1PS	3  1000*270 1PS	4  1000*270 1PS
5  900*270 1PS	6  900*50 1PS	7  900*80 2PS	8  900*80 1PS
9  900*80 1PS	10  910*162 1PS	11  910*264 2PS	12  898*255 1PS
13  866*100 1PS	14  765*240 1PS	15  765*240 1PS	16  765*120 1PS

17




765*120 1PS

18




863*120 1PS

19




831*120 1PS

20



693*120 2PS


21



898*497.5 4PS


"A" Hardware installation example

I




This part cannot be separated,
please install in strict
accordance with the assembly
requirements


II




III



IV



1



A*31















C*21


put A on board ①②③④⑤

put C on board ①⑤⑥⑦⑧⑨

2



A*24




C*8

put A on board 12 14 15 18 20

put C on board 13 14 15 16 17 19

3





Make sure the arrow on the screw align to the hole on the side.



B*12

put B on board 14 15 16 17

4





B*11



F*8

put B on board ⑥ ⑦ ⑧ ⑬





5



B*11

put B on board ①②⑤⑥⑦⑧⑨

6



B*11




H*8





I*8

put B on board ①②⑤⑥⑦⑧⑨

7




8



D*32




E*2



J*1



9



B*10

put B on board 19 20



10



G*4


11

X4



C*12

12



END

