




38" SQUARE TABLE P16-C


TOOLS




HARDWARE



PARTS




1




Attach cross pieces D & E to legs B using two 2 1/2" screws (BB) per cross piece.

2




Repeat step 1 for cross pieces F & G.

3



Insert cross pieces D, E, F & G in pockets on leg C and attach with two 2 1/2" screws (BB) per cross piece.

4



Attach table top A to table assembly from step 3. Use two 1/4" x 2 1/4" wafer bolts (AA) at each leg and finish with eight flange nuts (CC).