












A	x 16	B	x 16	C	x 12	D	x 4
φ6 x 35mm		φ15 x 12mm		φ8 x 30mm		M6 x 35mm	
E	x 3	F	x 3	G	x 2	H	x 6
4 x 25mm		φ12 x 12mm		3.5 x 35mm		M6 x 25mm	
I	x 10	J	x 26	K	x 4	L	x 1
φ7 x 40mm		3.5 x 16mm				M4	
M	x 4	N	x 12	O	x 2	P	x 2
		φ5 x 16mm		φ6 x 30mm			
Q	x 1						



1





A	x 6
	
$\phi 6 \times 35\text{mm}$	

J	x 2
	
$3.5 \times 16\text{mm}$	


Q	x 1
	

2



A	x 10
	
$\phi 6 \times 35\text{mm}$	


3



B	x 2
	
$\phi 15 \times 12\text{mm}$	

C	x 2
	
$\phi 8 \times 30\text{mm}$	


4



B	x 2
	
$\phi 15 \times 12\text{mm}$	


C	x 1
	
$\phi 8 \times 30\text{mm}$	

5




C	x 1	I	x 2	L	x 1
					
Ø8 x 30mm		Ø7 x 40mm		M4	

6




B	x 10	C	x 4
			
Ø15 x 12mm		Ø8 x 30mm	

7




C	x 2	I	x 4	L	x 1
					
Ø8 x 30mm		Ø7 x 40mm		M4	

8




B	x 2	C	x 2
			
Ø15 x 12mm		Ø8 x 30mm	

9



J	x 18
	
3.5 x 16mm	


10




D	x 4
	
M6 x 35mm	

L	x 1
	
M4	

K	x 4
	




11




H	x 6
	
M6 x 25mm	

I	x 4
	
ø7 x 40mm	

L	x 1
	
M4	



12




E	x 3
	
4 x 25mm	


F	x 3
	
ø12 x 12mm	

L	x 1
	
M4	


13



N	x 12
	
$\phi 5 \times 16\text{mm}$	




14




J	x 4
	
$3.5 \times 16\text{mm}$	

M	x 4
	

15



16



G	x 2
	
$3.5 \times 35\text{mm}$	

O	x 2
	
$\phi 6 \times 30\text{mm}$	

J	x 2
	
$3.5 \times 16\text{mm}$	

P	x 2
	