



Assembly Instruction















Attention: Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.



Hardware arts


A		M6x10mm	13	E		M6x45mm	8	I		M4X12	2
B		M6x12mm	8	F		M6x55mm	1	J		4#	1
C		M6x30mm	2	G		M8x15mm	12	K		5#	1
D		M6x40mm	4	H		M8x35mm	2				

Part list

	①	2 pcs		②	1pc		③	1pc		④	1pc		⑤	1 pc
	⑥	1 pc		⑦	2 pcs		⑧	2 pc		⑨	2 pcs		⑩	1 pcs
	⑪	2 pc		⑫	1 pcs		⑬	10 pc		⑭	1 pcs		⑮	2 pcs
	⑯	2 pcs		⑰	4 pcs		⑱	8 pcs		⑲	2 pcs			


Step: 1

E	 M6x45mm	6
J	 4#	1




Step: 3

I	 M4x12mm	2
K	 5#	1




Step: 2

A	 M6x10mm	3
B	 M6x12mm	8
E	 M6x45mm	2
J	 4#	1




Step: 4




Step: 5

G	 M8x15mm	8
K	 5#	1




Step: 6


D	 M6x40mm	4
C	 M6x30mm	2
F	 M6x55mm	1
G	 M8x15mm	4
H	 M8x35mm	2
J	 4#	1
K	 5#	1




Step: 7



Step:8




Step:9




Step 10


A		M6x10mm	10
J		4#	1



Step 11



Step 12



Step 13

