




Assembly Guide | Cube Storage

Parts List

| | | | |
|---|---|---|--|
|  Panels - A |  Feet - B |  Connectors - C |  Tools - Hammer |
|---|---|---|--|


Step 1



A x 1
C x 4


Make sure the connector is mounted with the correct orientation.

Step 2




A
B

Step 3




A x 5
C x 3

Step 4




A x 2
C x 3

Step 5



A x 5
C x 3

Step 6



A x 2
C x 3