


ASSEMBLY INSTRUCTIONS


ITEM NO.:N707P392140







IMPORTANT NOTE:

- ① PLACE ALL PARTS ON A CLEAN AND SMOOTH SURFACE SUCH AS A RUG OR CARPET TO AVOID THE PARTS FROM BEING SCRATCHED.
- ② BEFORE YOU BEGIN,KINDLY FOLLOW THE ASSEMBLY INSTRUCTIONS STEP BY STEP.
- ③ DO NOT TIGHTEN ALL SCREWS AND BOLTS UNTIL THIS ITEM IS FULLY SET-UP.

Detail View



N707P392140

1		2		3		4	
	1x		1x		1x		1x
5		6		7		8	
	1x		1x		1x		1x
9		10		11		12	
	1x		1x		1x		1x
13		14		15		16	
	1x		1x		1x		1x
17		18		19		20	
	1x		1x		1x		1x
21		22		23		24	
	1x		1x		1x		2x
25		26		27		28	
	2x		1x		1x		1x
29		30		31		32	
	1x		1x		2x		1x

33		34		35		36	
1x		1x		2x		2x	
37		38		39		40	
1x		1x		2x		2x	
41		42		43		44	
2x		1x		1x		2x	
45							
2x							

Hardware List



A	 Ø 3.5*60 16x	B	 Ø 3.5*40 26x	C	 Ø 3.5*35 2x	D	 Ø 3.0*30 10x
E	 Ø 3.0*28 34x	F	 Ø 3.0*18 6x	G	 Ø 3.0*16 20x	H	 Ø 3.0*10 2x
I	 Ø 6.0*20 24x	J	 Ø 6.0*60 9x	K	 Ø 6.0*55 5x	L	 Ø 6.0*45 6x
M	 Ø 6.0*35 2x	N	 Ø 6.0*16 2x	O	 2x	P	 16x
Q	 14x	R	 2x	S	 3x	T	 2x
U	 2x	V	 2x	W	 4x	X	 2x
Y	 4x	Z	 1x	AA	 1x		

ASSEMBLY TOOLS REQUIRED(NOT INCLUDED)



PLEASE BE CAREFUL DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWERTOOLS !


P*16



1

P*16

D*4
J*4
L*2



2

	
6.0*60MM	6.0*45MM
J*4	L*2



3.0*30MM
D*4

AA*1



3

A*6

Front





3.5*60MM
A*6




X2

B*18
I*24
X*2
Y*4
V*1




4

V*1	3.5*40MM B*18	6.0*20MM I*24	X*2	Y*4



5




A*2
C*2
J*5
K*5

6

3.5*60MM A*2	3.5*35MM C*2	
6.0*60MM J*5	6.0*55MM K*5	AA*1


M*2



6.0*35MM
M*2

7



E*12



3.0*28MM
E*12

8

A*4
N*2



3.5*60MM
A*4

6.0*16MM
N*2


9

A*4



3.5*60MM
A*4


10



F*6
G*4
R*2
S*2
V*1

	
S*2	V*1
	
F*6	R*2

11




B*8
G*2
S*1

		
B*8	G*2	S*1


12



L*4



O*2






	
L*4	AA*1

13


O*2

14

Q*14




15



Q*14

16

E*8



17

3.0*28MM

E*8

18

D*6



3.0*30MM

D*6


G*6



19

3.0*16MM

G*6

G*8
U*2


20

3.0*16MM

G*8



U*2

E*6
H*2
T*2

21

3.0*28MM

E*6


3.0*10MM

H*2



T*2

E*8




22

3.0*28MM


E*8

W*4
Z*1



23

W*4	Z*1



24