
















# 3PCS WICKER SWIVEL CONVEERSATION SET -SWIVEL CHAIR

Parts List :


NO.	part	Diagram	Qty pcs
A	Chair Back		2
B	Seat Panel		2
C	Left Arm		2
D	Right Arm		2
E	Chair Base		2
F	Chair Bracket		2
G	Screws	 M6*45mm	8
H	Screws	 M6*35mm	16
I	Nuts		8
J	Washers		24
K	Seat Cushion		2
L	Back Cushion		2
M	Allen Wrench		1
N	Wrench		1




1>:B+C+D




2> : A+BCD



3>:ABCD+F



4>ABCD+ E



5>ABCD+ E+K+L



The chair is full assembled now.