






































ASSEMBLING INSTRUCTION




ASSEMBLING INSTRUCTION



①L x1 		①R x1 		② x1 	③ x2 	④ x1 	⑤ x1 		
⑥ x2 		⑦ x10 		⑧ x1 	⑨ x1 	⑩ x1 			
⑪ x1 		⑫ x1 		⑬ x2 	⑭ x2 	⑮ x2 			
⑯ x1 		⑰ x1 		⑱ x2 	⑲ x2 	⑳ x2 			
A.x24  M6x10	B.x40  M6x25	C.x3  M6x55	D.x4  M6x80	E.x3  M6	F.x4 	G.x6 	H.x6 	J.x6 	K.x2 
L.x1  M6	M.x24  M4x22	N.x8  M4x25	O.x32  M4	P.x2 	Q.x4 	R.x1  M4	S.x1  M6	T.x1  M4	U.x4  M6x40


ASSEMBLING INSTRUCTION

1



A		M6x10	4
K			2


2



C		M6x55	3
E		M6	3


ASSEMBLING INSTRUCTION

3



H		4
---	---	---


4



A		M6x10	8
J			4


ASSEMBLING INSTRUCTION

5



B  M6x25 8


6



B  M6x25 12


ASSEMBLING INSTRUCTION

7



B		M6x25	10
G			6


8



A		M6x10	4
B		M6x25	6


ASSEMBLING INSTRUCTION

9



B		M6x25	4
F			4

10




U		M6x40	4
H			2
M		M4x22	24

N		M4x25	8	P		2
O		M4	32	Q		4

ASSEMBLING INSTRUCTION

11



A		M6x10	8
D		M6x80	4

12

