

















IMPORTANT INFORMATION:

1) REMOVE THE PROTECTIVE FOIL IF THE TABLE IS IN HIGH GLOSS

2) HIGH GLOSS SURFACE HARDENING TIME IS 2 HOURS









3) AFTER 2 HOURS, TO CLEAN THE SURFACE, USE ONLY SOFT CLOTHS (E.G. COTTON OR MICROFIBRE CLOTHS AVAILABLE IN STORES). WASH THE SURFACE WITH A 1% MIXTURE OF SOAPY WATER





L  x2	M  7 x 50 x20	N  x20			
G  x10	H  x4	I  4 x 15 x8	J  6,3 x 13 x30	K  x1	
A  7 x 70 x12	B  8 x 30 x24	C  x4	D  x1	E  x1	F  x1

1


x2





II




III




IV




V




VI




VII



VIII



IX



X

