



$\frac{43.5}{1.7}$




Ax1

$\frac{43.5}{1.7}$



Bx1


$\frac{43.5}{1.7}$



Cx1

$\frac{43.5}{1.7}$

Dx1




$\frac{662.5 \times 179}{26.1 \times 7.0}$

Ex4




$\frac{381 \times 179}{15.0 \times 7.0}$

Fx2



Gx1




Hx5



Ix2



Jx2



304x250
12.0x9.8


Kx2




Lx2




Mx4




DRx2



DLx2



CRx2



CLx2



Nx48



Ox48



Px32



Qx110



Rx7



Sx1



Tx16




Ux2




Vx4



Wx1





Xx1



mm
inch

x2

1





CLx1

Tx2



2





CRx1


Tx2



3




4




Ox7



5




Nx7



Px7




6



Ox7




7



A

a



Tx2



CLx1

CLx1

Tx2



8




CRx1


Tx2




9




Nx7



Px7




10




Ox7



11



Nx7




Px7



a


(12)




Ox7



(13)




Nx4



Px4




14



Ox4



15




Qx90

Qx90



⑯




Rx4




Vx4



Rx1






Vx1




x4

⑰




x2




90°

(18)




Nx16



x2

(19)





Ox16




x2


(20)




(21)






(22)



(23)



(24)



(25)

