












EN_IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.


NO.	PARTS	QTY	SPARE
①		x1	
②		x1	
③		x1	
④		x4	
⑤		x6	
⑥		x3	
⑦		x3	
	 Hardware Kit	x1	



[illegible]







A x22 $\varnothing 4 \times 40 \text{ mm}$ +2(spare)	B x36 $\varnothing 3.5 \times 12 \text{ mm}$ +3(spare)	C x4 $\varnothing 6 \times 30 \text{ mm}$	E-1	E-2	E x6 $M6 \times 12 \text{ mm}$	F x20 $\varnothing 15 \text{ mm}$ +2(spare)
G x1 $M5$	H x2	I x2 $\varnothing 6 \times 30 \text{ mm}$	J x6 $\varnothing 4 \times 10 \text{ mm}$	L x3	R x3	

01










B x18
Ø3.5x12mm


L x3

R x3

⑦ x3

B x6
Ø3.5x12mm


⑥ x3



07

B x6
Ø3.5x12mm

⑤ x3




08

E x4
M6x12mm




E-2

E-3



G x1
M5

B x4
Ø3.5x12mm


5 x2



OR



OR



A x2
Ø4x40mm

I x2
Ø6x30mm



WALL

I x2

WALL +


drilling hole
Ø6x30mm

II x2






WALL

III x2




WALL







B x2
Ø3.5x12mm



5 x1



WALL



OR



OR

