

It is normal for the sealed environment to smell, not a product quality problem.

Phone number: 303-747-4421 / (951) 213-4743

service@clihome.net
Web:www.clihome.net

#### Part List:

ITEM	DESCRIPTION	PART	QTY
1	Top panel		1
2	Bottom panel		1
3	Left side panel		1
4	Right side panel		1
5	Back panel		1

### Part List:

TOTO BISC:				
ITEM	DESCRIPTION	PART	QTY	
6	Leg		4	
7	Left door		1	
8	Right door		1	
9	Adjustable shelf		1	

## Hardware List:

ITEM	DESCRIPTION	PART	QTY
A	Wooden dowel	Ф8*30mm	8
В	Bolt	Φ1/4"*1"	4
С	Bolt	<b>Φ</b> 1/4"*1/2"	16
D	Allen wrench		1
E	Door fitting		4
F	Round head screw	<b>Ф</b> 3*12mm	24
G	Handle		2

## Hardware List:

ITEM	DESCRIPTION	PART	QTY
Н	Machine screw	Φ5/32″*3/4″	4
Ι	Back screw	<b>Ф</b> 3*15mm	20
J	Shelf support		4
K	Safety wall strap		2
L	Plastic anchor		2
M	Mounting screw	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	2
N	Washer	0	2

- \* Required screwdriver & mallet, not included.
- \* Before discarding packing materials, please check to make sure that all parts and hardware is present.
- \* Two people needed for assembly.
- \* Please follow the instructions closely; do not over tighten screws or bolts unless instructed.
- \* After a few days from initial assembly, the product may have acclimated to the new environment. Please retighten the hardware.

#### Guideline For Assembling of Plastic Lock













