








ASSEMBLY INTRODUCTION




Exploded View




Fittings

 A x 58 <i>M6 x 35 mm</i>	 B x 58 <i>φ15 x 9.5 mm</i>	 C x 18 <i>φ6 x 30 mm</i>	 D x 32 <i>φ4 x 35 mm</i>	 E x 72 <i>φ3 x 12mm</i>
 F x 5 <i>φ6 x 50 mm</i>	 G x 2 <i>35 x 35 mm</i>	 H x 4 <i>φ4 x 12 mm</i>	 I x 2 <i>φ6 x 30 mm</i>	 J x 2 <i>φ4 x 40 mm</i>
 K x 12	 CL x 6 <i>300 mm</i>	 CR x 6 <i>300 mm</i>	 DL x 6 <i>300 mm</i>	 DR x 6 <i>300 mm</i>






Step 1





Step 2






Step 3




Step 4






Step 5




Step 6




Step 7






Step 8




Step 9






Step 10







Step 11



Step 12





Step 13





Step 14

x6




Step 15

x6




Step 16




x6




Step 17
x6




Step 18
x6



E x 36
x 12 mm




DL x 6
300 mm



DR x 6
300 mm

Step 19



Step 20

