

OPERATIONS MANUAL



Assembly and Installation Steps


Step 1

- 1A. Lock the crossbar to the junction box of the ceiling by using 2 pcs of 5/32 screws in the accessories bag.
 1B. Connect the wires. The hot/positive wire (+) has an "L" label on it. The other one is the negative wire (-). And the bare cooper is the ground wire.
 1C. Attach the canopy to the ceiling with screws



Step 5

Buckle the crystal ball and hang the crystal string on the metal ring. The recommended installation sequence is from 76 to 1



Please note that the length of suspension line 1 is the shortest and that of suspension line 76 is the longest. The bigger the number, the longer the suspension line.

