

NOTICE

- * Please make sure that you have all parts indicated and they are in good condition before you begin assembly of this item. Refer to part list and hardware list below for guidance.
- *This item should be assembled on the ceiling to prevent scratching the finish during assembly.
- *To reduce the risk of fire, electrical shock or injury to persons or property, please follow the guideline below for safe use and installation.

PREPARATION

- *Before beginning assembly of product, make sure all parts are present. Compare parts with part contents list and hardware contents list.
- * If any part is missing or damaged, do not attempt to assemble the product.
- * Estimated Assembly Time: 3 minutes.
- * If you are having difficulty, our friendly Customer Care team is always here to help.


CARE AND MAINTENANCE

- * Unplug lamps before using any cleaning solutions.
- * Dust shades with a feather duster or with an appropriate vacuum brush attachment.
- * Wipe with a soft, dry cloth and clean lamp bases with the methods appropriate to the material.
- * Avoid the use of chemicals and household cleaners as they may damage the finish.

Part List and Hardware List

PEICE	DESCRIPTION	PICTURE	QUANTITY	PEICE	DESCRIPTION	PICTURE	QUANTITY
A	Lamp Base		1X	D	Socket		1X
B	Glass Shade		1X	E	Light Bulb		1X
C	Ring		1X				




Product Dimensions:: :10"X6.25"X20"



PREPARATION

- * Before beginning assembly of product, make sure all parts are present. Compare parts with part contents list and hardware contents list.
- * If any part is missing or damaged, do not attempt to assemble the product.
- * Estimated Assembly Time: 3 minutes.
- * If you are having difficulty, our friendly Customer Care team is always here to help.

NOTE:PLEASE USE TYPE"A" BULB MAX 60-WATT OR CFL BULB MAX 23-WATT OR LED BULB MAX 12-WATT,THERE IS LED 9-WATT BULB IN THE BOX

		
Step 1:Install the Glass shade(B) into the Socket(D) and fix it with the Ring(.C)	Step 2: Install the light bulb(E) into the socket(D) by clockwise.	Step 3:Put the light on a level surface to check ,if everything is stable.