

























ASSEMBLY INSTRUCTIONS




Part List

				
① x2Pcs	② x2Pcs	③ x4Pcs	④ x1Pc	⑤ x1Pc
				
⑥ x1Pc	⑦ x1Pc	⑧ x1Pc	⑨ x2Pcs	⑩ x8Pcs
				
⑪ x1Pc				


Hardware List

				
Ax6Pcs	Bx6Pcs	M6x50 Cx12Pcs	M6x30 Dx40Pcs	Ex12Pcs
				
Fx1Pc	M6 Gx8Pcs	Hx8Pcs	Kx1Pc	M6x35 Lx8Pcs
				
Mx1Pc				




PLEASE BE CAREFUL. DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWER TOOLS !


Step 1



M6
Gx8Pcs




Step 2




Fx1Pc






M6x35
Lx8Pcs




Step 3







	
Kx1Pc	Ax6Pcs



Step 4



			
Mx1Pc	Ex4Pcs	Kx1Pc	Bx2Pcs

Step 5




Ex4Pcs




Kx1Pc



Bx2Pcs




Step 6



Hx8Pcs




Ex4Pcs





Kx1Pc




Bx2Pcs






Step 7

	
Fx1Pc	M6x50 Cx12Pcs






Step 8

	
Fx1Pc	M6x30 Dx8Pcs




Step 9

	
Fx1Pc	M6x30 Dx32Pcs



Step 10


Mx1Pc

