






Assembly Instruction

Model No. : ZW-25109-3S

	Parts supplied	Graphic	Qty		Hardware supplied	Graphic	Qty
Ⓐ	side leg		4	①	M6*3.5 screw		12
Ⓑ	middle leg		1	②	Φ5mm screw		32

Step 1



Step 2

