



ASSEMBLY INSTRUCTIONS




TURN TOP UPSIDE DOWN ON A SOFT WORKING SURFACE

<p>①</p>	<p>②</p>	<p>③</p>
<p>④</p>	<p>⑤</p>	
<p>A</p> <p>x4</p>	<p>B</p> <p>x1</p>	

STEP1




STEP2



Hardware & Tools Required

STEP3



STEP4

