




ASSEMBLY INTRODUCTION


















Plate





Plate





Fitting

A x 36 +2  M6 x 35 mm	B x 36 +2  φ15 x 9.5 mm	C x 34 +2  φ6 x 30 mm	D x 8 +1  φ4 x 30 mm	E x 50 +4  φ3.5 x 12mm
F x 4 	G x 8  φ4 x 20 mm	H x 2  26 mm	I x 4  φ5 x 17 mm	J x 12 +1 
K x 2 	L x 12 +1  φ4 x 14mm	M x 2 	N x 2 	O x 8  φ7 x 50 mm
P x 1  4 mm	R x 3 	S x 2  φ3 x 12mm	T x 2 	U x 16 +1  φ3 x 14 mm
CR x 2  300 mm	CL x 2  300 mm	DR x 2  300 mm	DL x 2  300 mm	

1




2



3

A x 6




4


B x 6



C x 6





5



6

A x 6



7


C x 6



O x 6




P x 1




8

A x 2



9

B x 2



10

A x 3







E x 12



CL x 2




CR x 2



11

A x 3



12


C x 2





O x 2




P x 1




13





14



15




16




17

L x 8




18

I x 4




19

D x 8




20



21

A x 8




22


B x 8



F x 2




G x 4




23



E x 8




DR x 2



DL x 2



24




25

J x 12



U x 12



26

E x 9



F x 1



G x 2





R x 3



S x 2





T x 2



27

E x 9








28






E x 10



K x 2









**Customer Attention:**



To align doors and control gap in between doors. Product doors may need adjusting during and after assembly.

This can be done by adjusting appropriate screws. See below illustration.



**Vertical Door Adjustment:**

Loosen both screws on all hinges and lift the door to the desired height.

This allows an even space at the top and bottom between the door and frame.

**Lateral Door Adjustment:**

If door is hinge bound, (rubbing on frame as you close or open door) loosening screw shown and move the door in appropriate direction. (In or out)

**Horizontal Door Adjustment:**

Rotate Screw clockwise or anticlockwise.

This will produce an even gap between doors and frame.