










# PART LIST

<p><b>1</b> x2</p> 	<p><b>2</b> x2</p> 
<p><b>3</b> x8</p> 	<p><b>4</b> x2</p> 
<p><b>5</b> x2</p> 	<p><b>6</b> x2</p> 
<p><b>7</b> x2</p> 	<p><b>8</b> x2</p> 

# PART LIST


9

x1




10

x1




11

x1




12

x6




13

x3
















14

x2




# PART LIST


<b>A</b>	<b>B</b>	<b>C</b>	<b>D</b>	<b>E</b>	<b>F</b>	<b>G</b>
 <p>M6x23</p>	 <p>M4x12</p>		 <p>M6.3x50mm</p>	 <p>Ø 6x30mm</p>		
x56	x2	x22	x4	x2	x8	x11
<b>H</b>	<b>I</b>					
						
x1	x2					
<b>J</b>	x1					
						
<b>K</b>	x1					
						
<b>L</b>	x11					
						
<b>R</b>	x11					
						

# ASSEMBLY INSTRUCTION


1




x2



2




x2




# ASSEMBLY INSTRUCTION

3




x2




A

x4

4



x2




F


x4

# ASSEMBLY INSTRUCTION



5



x2





6





# ASSEMBLY INSTRUCTION

7





8





# ASSEMBLY INSTRUCTION

9





10





10

# ASSEMBLY INSTRUCTION

11




12




# ASSEMBLY INSTRUCTION

13






14




# ASSEMBLY INSTRUCTION

15




C		G	
	x6		x3

16




# ASSEMBLY INSTRUCTION

17






18




# ASSEMBLY INSTRUCTION


19



B		J	
	x2		x1

20



I	
	x2

Trouble shooting:

Missing /Wrong / Broken parts and installation issues



Send email with your question, pic and order NO.to **support@garvee.com**



Respond within 24 hours



Issue resolved