

Ax1 	Bx1 	Cx1 	Dx1 	Ex1
Fx2 	Gx2 	Hx2 	Ix1 	Jx1
Kx1 	Lx1 	Mx2 	Nx2 	Ox2
Px4 	Qx4 	Rx2 	Sx1 	Tx1
Ux2 	Vx3 	Wx3 	Xx2 	Yx1
Zx40 M3x $\frac{25}{1.0}$	AAx21 M3x $\frac{20}{0.8}$	ABx12 M2x $\frac{10}{0.4}$	ACx36 M2.5x $\frac{18}{0.7}$	
① AA x2	② AB x4	③ AA x1 mm inch x2		
④ Z x4	⑤ Z x4	⑥ AA x4		

<p>7</p>	<p>8</p> <p>Zx8</p> <p>F</p> <p>R</p> <p>F</p> <table border="1"> <tr> <td>Z</td> <td>x8</td> </tr> </table>	Z	x8	<p>9</p> <p>G</p> <p>G</p>										
Z	x8													
<p>10</p> <p>T</p> <p>ACx4</p> <p>ACx4</p> <p>S</p> <p>Ux2</p> <table border="1"> <tr> <td>AC</td> <td>x8</td> </tr> </table>	AC	x8	<p>11</p> <p>AAx4</p> <p>10</p> <table border="1"> <tr> <td>AA</td> <td>x4</td> </tr> </table>	AA	x4	<p>12</p> <p>Px4</p>								
AC	x8													
AA	x4													
<p>13</p> <p>ACx12</p> <p>AAx4</p> <p>H</p> <p>H</p> <table border="1"> <tr> <td>AC</td> <td>x12</td> </tr> <tr> <td>AA</td> <td>x4</td> </tr> </table>	AC	x12	AA	x4	<p>14</p> <p>K</p> <p>V</p> <p>AAx2</p> <p>N</p> <p>AA</p> <p>W</p> <p>ABx4</p> <table border="1"> <tr> <td>AB</td> <td>x4</td> </tr> <tr> <td>AA</td> <td>x3</td> </tr> </table>	AB	x4	AA	x3	<p>15</p> <p>AAx2</p> <p>V</p> <p>L</p> <p>N</p> <p>W</p> <p>AA</p> <p>ABx4</p> <table border="1"> <tr> <td>AB</td> <td>x4</td> </tr> <tr> <td>AA</td> <td>x3</td> </tr> </table>	AB	x4	AA	x3
AC	x12													
AA	x4													
AB	x4													
AA	x3													
AB	x4													
AA	x3													
<p>16</p> <p>Zx6</p> <p>M</p> <p>I</p> <p>14</p> <table border="1"> <tr> <td>Z</td> <td>x6</td> </tr> </table>	Z	x6	<p>17</p> <p>15</p> <p>J</p> <p>M</p> <p>Zx6</p> <table border="1"> <tr> <td>Z</td> <td>x6</td> </tr> </table>	Z	x6									
Z	x6													
Z	x6													

