










A x28
Spec: $\varnothing 12 \times 50$



B x4
Spec: $5/16 \times L75$




C x16
Spec: $\varnothing 8 \times \varnothing 14$



D x8
Spec: $\varnothing 55 \times 12$



E x8
Spec: $\varnothing 3.8 \times L22$



F x1
Spec: 5#




G x2
Spec: 10g



H x1
Spec: 4#




I x4
Spec: $M8 \times L865$



J x4
Spec: $M8 \times L970$





K x4
Spec: $M8 \times L420$




1

2






3



4



6

