


► SCREW PACKAGE



M6x12(x4)

A




(x1)

D



M6x35(x4)

B




(x2)

E



(x1)


C



(x2)


F

► PARTS INCLUDED




x1

G



x1

H



x1



I

ASSEMBLY INSTRUCTIONS





► SCREW PACKAGE



1



2



3



4

