

ASSEMBLY INSTRUCTIONS






Important reminder:

- \triangle Please sort and check all accessories before assembly.
- \triangle Please place the product on empty cardboard box or carpet to avoid scratches on it,
- △Please use proper tools for assembly. Using an electric screwdriver can accelerate the assembly speed, but please do not overtighten the screws.
- \triangle Please follow the assembly steps and do not skip any of them.
- \triangle If possible, please find a partner to help you with assembly, which can accelerate assembly.
- ∆ Keep all small parts of this product away from children.
 They may cause serious injury.
- \triangle We hope you can retighten the screws 2 weeks after assembly, and check the tightening procedure of the screws every 3 months.

If you meet any difficulty, our friendly customer team are always ready to help you.












Warning:Overturning the product can cause serious crushing injuries. We have a wall connection device attached, please use it to hold the furniture following assemblyinstructions. Do not change the structure of this product inway. Our products have been testedand meetanyallsales specific security measures. We won'tbe responsible for any modifications, whichmay cause significant security risks.


Explosion Diagram



Explosion Diagram











HardWare LIST						
M6*10mm	M6*25mm	M6*35mm	M6*30mm			
A 126PCS +6PCS	B 4PCS +1PC	C 16PCS +1PC	D 2PCS +1PC			
M8*15mm	M8*50mm	M6*5mm	M8*7.8mm			
E 4PCS +1PC	F 4PCS +1PC	G 18PCS +2PCS	H 6PCS ^{+1PC}			
ø16*1.5* ø 9mm	M6*50mm	K1 K2 K4	Ø6*40mm			
I 8PCS +1PC	J 40PCS +2PCS	K 2PCS	L 20PCS +2PCS			
Ø8*40mm	N2 N1 50*10*20mm ST3. 5*30mm	01 02 02	ST3. 5*14mm			
M 6PCS +1PC	N 2PCS	O 2PCS	P 24PCS ^{+3PCS}			
Q1 Q2 150*125*45 ST3. 5*40mm	R1 R2 M4*22mm	635* Ø 28 (1400N)	T1			
Q 2PCS	R 2PCS	S 2PCS	T 2PCS			
U1 U2	S4	S4 (100*40)	V			
U 4PCS	V 2PCS	W 1PC	X 1PC			
	Tips: The number after "+" represents the spare hardware. please check all hardware on board again. If you encounter any problems during installation please contact our					


HardWare LIST						
,	10#	13#				
Y	1PC	Z 1PC				
<u></u>	Tips: The number after "+" represents the spare hardware. please check all hardware on board again.					














13 90°

