ASSEMBLY INSTRUCTIONS - BM307287

(BOX 1)

BOX OF HEADBOARD


ITEM	DRAWING	DESCRIPTION	QTY
А		HEADBOARD	1
В		HEADBOARD INNER LEG SUPPORT	2
С		HEADBOARD LEG SUPPORT	2

(BOX 2)

BOX OF HEADBOARD LEG


ITEM	DRAWING	DESCRIPTION	QTY
D	F .	HEADBOARD LEG - RIGHT	1
E	P S	HEADBOARD LEG - LEFT	1

(BOX 1)





COMPLETED HEADBOARD ASSEMBLY



NOTE : MUST TIGHTEN THE BOLTS & SCREWS PERIODICALLY. WITH USE BOLTS & SCREWS MAY BECOME LOOSE. CHECK TIGHNESS OF ALL BOLTS & SCREWS EVERY 6-8 WEEKS.

CLEANING INSTRUCTION

After assembly, clean & polish the completed parts if necessary with soft cloth and industrial recognized furniture polish

ASSEMBLY INSTRUCTIONS- BM307287

(BOX 1) BOX OF FOOTBOARD

ITEM	DRAWING	DESCRIPTION	QTY
А		FOOTBOARD	1
В	٩	BUN FOOT	2
С	/	WOODEN SLAT	4
D	Į	WOODEN SUPPORT WITH ADJUSTER	8

(BOX BOX (ITEM E

2) OF SIDE RAIL			
1	DRAWING	DESCRIPTION	QTY
		SIDE RAIL	2


(BOX 1) HARDWARE LIST

ITEM	DRAWING	DESCRIPTION	QTY
1		ALLEN KEY (M4)	1
2		ALLEN KEY (M5)	1
3		CONNECTION BOLT (M8 x 30mm) W/SPRING WASHER & WASHER MEDIUM	8
4		CONNECTION BOLT (M6 x 40mm)	8
5	Shannan	CSK SCREW (M4 x 32mm)	8
6		SCREW DRIVER (*)	1



ASSEMBLY

(*) The Manufacturer does not provide item 6.




THE HARDWARE IS LOCATED IN THE PACKING ITEMS.

NOTE : MUST TIGHTEN BOLTS & SCREWS PERIODICALLY. WITH USE BOLTS & SCREWS MAY BECOME LOOSE. CHECK TIGHNESS OF ALL BOLTS & SCREWS EVERY 6-8 WEEKS.

CLEANING INSTRUCTION

After assembly, clean & polish the completed parts if necessary with soft cloth and industrial recognized furniture polish

ASSEMBLY INSTRUCTIONS - BM307287



THE HARDWARE IS LOCATED IN THE PACKING ITEMS.

NOTE : MUST TIGHTEN BOLTS & SCREWS PERIODICALLY. WITH USE BOLTS & SCREWS MAY BECOME LOOSE. CHECK TIGHNESS OF ALL BOLTS & SCREWS EVERY 6-8 WEEKS.

CLEANING INSTRUCTION

After assembly, clean & polish the completed parts if necessary with soft cloth and industrial recognized furniture polish